#### South Cove 2025 I

Number of Units: 46

Level of Service : Level I

Report Period: FY 2024-2025

Projection Period: 2025-2055

## **Current Status - January 1, 2025**

Projected Reserve Balance: \$8,660

Fully Funded Balance: \$147,955

Percent Funded: 6%

### **2024 Current Funding Plan**

Monthly Contribution: \$0

Special Assessment: \$0

# **2025 Budget Recommendation**

Recommended Plan: Full Funding

Monthly Contribution: \$1,390

Special Assessment: \$0

### **Summary Notes**

The Association will need to establish a contribution of \$31.59 per paying Lot per month to get onto the path to becoming Fully Funded in 2054 and have sufficient funds in the Reserve Account to maintain, repair or replace the Common Elements when needed.

## Key

FFB	Fully Funded Balance or the value of
	the used portion of the component


RUL Remaining Useful Life or years before

replacement

5 Year Reserve Fund Projections										
	Year	2025	2026	2027	2028	2029				
	Reserve Expenses	\$8,060	\$2,575	\$530	\$546	\$9,567				
	Annual Contributions	\$0	\$0	\$0	\$0	\$0				
CURRENT	Special Assessment	\$0	\$0	\$0	\$0	\$0				
	Ending Balance	\$606	\$0	\$0	\$0	\$0				
BASELINE	Annual Contributions	\$13,904	\$14,321	\$14,751	\$15,193	\$15,649				
	Special Assessment	\$0	\$0	\$0	\$0	\$0				
	Ending Balance	\$14,580	\$26,518	\$41,073	\$56,201	\$62,828				
	Annual Contributions	\$16,679	\$17,179	\$17,695	\$18,226	\$18,772				
FULL	Special Assessment	\$0	\$0	\$0	\$0	\$0				
	Ending Balance	\$17,368	\$32,206	\$49,776	\$68,039	\$77,923				



Reserve Study One Page Summary



# <u>Notes</u>

Top 10 Components with the Biggest Impact

These components have the most impact on your Reserve Funding due to their high

#### **Top 10 Upcoming Projects**

These projects are anticipated to be needed soon. Time to inspect, research, price and begin planning for these projects now. Update the reserve study as needed

Component	COST	RUL	Component	COST	RUL
Fence: Chainlink, Replace	\$7,560.00	0	24" Drainage Line: Replacement	\$130,000.00	25
Dock Surface: Repair	\$500.00	0	Fence: Wood, 6', Replace	\$99,700.00	10
Irrigation System: Repair/Replace	\$2,000.00	1	Fence: Chainlink, Replace	\$7,560.00	0
Retention Pond	\$6,000.00	4	Mailbox Structure: Repair/Replace	\$7,000.00	5
Mailbox Structure: Repair/Replace	\$7,000.00	5	Retention Pond	\$6,000.00	4
Lights: Pole, Replace	\$4,000.00	5	Entry Sign: Replacement	\$4,500.00	10
Fence: Wood, 6', Replace	\$99,700.00	10	Lights: Pole, Replace	\$4,000.00	5
Entry Sign: Replacement	\$4,500.00	10	Irrigation System: Repair/Replace	\$2,000.00	1
24" Drainage Line: Replacement	\$130,000.00	25	Dock Surface: Repair	\$500.00	0

Mailbox Locking Individual: Replace